

**r. R. RAMASAMY** B.E., M.Sc. (Val) M.I.E., F.I.V.,

Chartered Civil Engineer & Govt. Regd. Valuer

Income Tax & Wealth Tax Valuer C.I.324/95

F.I.V. No.F4614&M.I.E.No.M122897-2

IBBI / RV / 02 / 2019 / 11194

T.N.Govt. Practicing Engineer Class 1A | THIC Valuer

Approved Bank Panel Valuer in :

K.V.B., L.V.B., Bank of India, Canara Bank, Canfine Home, Axis Bank, Syndicate Bank, Karnataka Bank, Oriental Bank of Commerce, Bank of Baroda, South Indian Bank, Dhanalakshmi Bank, Allahabad Bank, Vijaya Bank, Corporation Bank, CUB, Bank of Maharashtra, I.O.B., State Bank of India, Tamilnadu Mercantile Bank, LIC(HFL), LIC & IDBI, United Bank of India.

RR Complex, 76, New Salem Bye-pass Road West, (Near Jairam School), Karur - 639 002, Ph : 04324 - 294699

99524 - 10279 | 77081 - 08099 | 94433 - 57199 | 99522 - 28899 | [errkr@gmail.com](mailto:errkr@gmail.com)

Date :

**ANNEXURE**

This is to certify that I have personally inspected the building and structures of **SIDDHARTH PUBLIC SCHOOL (CBSE SCHOOL)**, in S.F.No.325/1B & 326/3B2C, Thanneerpalli, Kulithalai, NH67 Trichy new Bypass Road, Rajendram North Village & Panchayat, Kulithalai Tk., Karur Dt., including compound wall have been covered by Stability certificate issued by me on 17.10.2020. There is no structure in the building used or unused which is not safe for the students.

Place : Karur.

Date : 17.10.2020



*R.R. Ramasamy*  
ENGINEER

**ER. R. RAMASAMY, B.E., M.I.E., F.I.V.,**  
CLASS - 1A, P-4.101 / 17366 / 2013  
R.R. COMPLEX,  
76, New Salem Bye - Pass Road,  
KARUR - 639 002.